



Pacific Regional Visitor Center,

Fort Derussy

March 15, 2002

Photos #1 & #2 are views of the new metal canopy roof entry way. An opening at the ground floor was created and new doors, transom and sidelite installed.

Photo #3 shows the new section of glass railing installed to open up the visibility of the RVC from the ground.





Interior Views of Pacific Regional Visitor Center

Photos #1,#2 & #3 shows the interior view of the newly renovated Visitor Center.

Photo #4 shows the new Information/Attendant Booth in the foreground, with the Multi-Media Theater in the background.

Photo #5 is the South wall where new displays are scheduled to be hung.

Photos #6 & #7 show the new 10 foot long salt water aquarium installed, which enhances the museum as well as acting as an object to attract visitors into the museum.

